



6 General comments about executed installations

Installations look really good.
Well done and good workmanship!

It's a privilege to see quality rising from already high level in phase 1.
A lot of work done by different parts in project gives result: good quality of installations.
Best I have seen in Poland so far!

- Garage installations very well coordinated.
- Trunking very good quality including turns, sharp edges, protection, sizes etc.
- Transformers, boards, bus-bars and switchgears looks really nice.
- Technical rooms for Mechanical installations well coordinated.
- Lighting in garage looks good.
- Tenant area well done installation above suspended ceiling.
- Main technical rooms in B4 (-1) should have been bigger sized.
To small technical room allowed by architect.
Installations really tough to do but despite that well done. Good!